



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program March 20, 2013

Reviewed:

Mine Name: Copperton Concentrator	Permit Number: M/035/0011
Operator Name: Kennecott Utah Copper	Inspection Date: March 10, 2011
Inspector(s): L Heppler, P Brinton	Time: 8:00 am
Other Participants: Zeb Kenyon - Kennecott	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 09-29-2012 **Bond Amount:** \$27,727,237 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection. This site was inspected as a large mine site on 12/02/2009.

Inspection Summary: Access to site was limited by a gate. Permit site was clean and well maintained. No trash was noted on site, and only minimal bone yards. No erosional problems were noted. Concurrent reclamation is not feasible at this time, but operator has maintained a minimal disturbance without impacting either production nor safety.

Photos were taken to document site conditions.

Conclusions and Recommendations: OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:eb

cc: Kennecott - Kelly Payne

O:\M035-SaltLake\M0350011-CoppertonConcentrator\inspections\Insp-03102011.doc





Copperton Concentrator – looking weest



Close up of Copperton Concentrator



Lower end of the concentrator



Lower end of the concentrator